




FIELD SERVICE BULLETIN



NORTH AMERICAN AVIATION, INC • MUNICIPAL AIRPORT • LOS ANGELES 45, CALIF.

NO. 18
*REVISED FEB. 14, 1947

*MANDATORY - MUST BE
ACCOMPLISHED BY 3-23-47

GENERATOR TERMINAL INSULATOR INSTALLATION

Effective on all airplanes.

DELIVERED AIRPLANES AFFECTED:

NAV-4-2 through NAV-4-411

This installation will be made at the factory on airplanes NAV-4-412 and subsequent.

In order to prevent contact between the generator lower terminal and the fitting on the hydraulic pump inlet hose, resulting in a short circuit, the 145-54053 self-threading insulator should be installed by screwing it on the generator lower terminal stud.

Compliance with this bulletin must be entered in the airplane log book.

JOHN W. CASEY
FIELD SERVICE MANAGER

If you have sold your NAVion, please return this part to the factory with name and address of the new owner.