



Navion Service Letter No. 90  
June 14, 2023

**Subject:** Usage of 6.50-8 6-ply main landing gear tire in place of 7.00-8 4-ply tire due to availability.

**Contact:** Sierra Hotel Aero, Inc. 1690 Aeronca Ln, South Saint Paul, MN 55075  
Phone: 651-306-1456 Email: [engineering@navion.com](mailto:engineering@navion.com)

**Effectivity:** Serial Number NAV-4-002 and Subs.

**Purpose:** Main landing gear tire replacement options for all model Navions to mitigate possible tire manufacturer inventory shortages.

**Description:** The usage of 6.50-8 6-ply tires are originally listed as approved for use on Navion G and H Models (Ref. TC A-782 Note 201). It is acceptable to use 6.50-8 6-ply tires on Navion aircraft S/N 002 and up.

**Note:**

- 1. Tires used must be the same size left side to right side.**
- 2. Inner Tubes must be used in the tire installation.**

**END**